**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

61301

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency .....

Date of commencement of work .....

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Name of work :- providing drinking water works in Ward NO. 13 in Dasarahalli Division. | | | | | | |
| | W.O :- BBMP/EE/DD/WO/93/2017-18, | | | | | 05-06-2017. | |
| | Job code :- 013-17-00 0052 | | | | | | |
| | AA :- CE/AS/16/17-18 | | | | 01-06-2017. | | |
| | TS :- EE/TS/10/17-18 | | | | 03-06-2017 | | |
| | AGY :- EE/DD/AGR/93/2017-18. | | | | | 05-06-2017. | |
| | Est cost :- 13.00 Lakhs | | | | | | |

Scanned by CamScanner

**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

Serial No. ..... 61304

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc, of work | | Dimensions | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Column $C_1$ | 4 | 0.2 | 0.38 | 2.75 | 0.84 | |
| | Lintel Beam Wall | 1 | 13.60 | 0.2 | 0.2 | 0.54 | |
| | Column $C_2$ | 4 | 0.2 | 0.35 | 0.3 | 0.08 | |
| | Roof Beam Beam #1 | 2 | 4.00 | 0.20 | 0.35 | 0.56 | |
| | Beam #2 | 2 | 4.00 | 0.20 | 0.35 | 0.56 | |
| | Roof slab | 1 | 4.00 | 4.00 | 0.15 | 2.40 | |

Scanned by CamScanner

# MEASUREMENT BOOK

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | | 1 | - | - | - | 1.00 | Each |
| | | @ RS 525.00 | | | | => | 525=00 |
| 50. | Insulated cable on messenger wire using 2 Single core wires for a single phase and 4 Single core wires for 3 phase. supplying and stringing PVC Insulated & PVC sheathed 650/1100 V. It is completed as per specification. | | | | | | |
| | | 1.00 | 30 | - | - | 30.00 | Rmt |
| | | @ Rs. 85.00 | | | | => | 2550=00 |

Checked
11/1/2018

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೆಬ್ಬಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

Serial No. ..... 61320

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | | | | Total | => | Rs. | 11,41,055=00 |
| | | | KRIDL | charges 10+ 1% | => | | Rs. 1,25,516=00 |
| | | | | Grand Total | => | Rs. | 1266571=00 |
| | certificate :- certified that works is satisfactory. | | | | | | |

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner